

Straight coupling.



Reference	tooltiplmage	Box units	measurement
355003	-	25	50
355004	-	20	63
355017	-	100	20
355018	-	100	25
355019	-	50	32
355020	-	50	40
355021	-	5	75
355022	-	5	90
355165	-	2	110
7355017	-	25	20
7355018	-	25	25
7355019	-	25	32