

# Optical position indicator



Κωδικός Προϊόντος	tooltiplmage	To be used with:	DN
OPI01	-	FE/FK DA	40 ÷ 150
OPI02	-	FE/FK DA	200 ÷ 300
OPI03	-	FK/DA	350 ÷ 400
OPI04	-	FK NC	350 ÷ 400

# Optical position indicator

- Upper part (PVC-U)
  - Bottom part (PVC-U)
  - Bolts (zinc plated steel)
  - Nuts (zinc plated steel )
  - Gasket (NBR)
  - Reinforcing ring (Stainless steel)
- The reinforcing bush are used to reinforce the pipe PE100 (SDR11) e PE-X, to along the lifetime of the pipeline and to reduce the collapse risk of the pipe in disadvantages conditions. They use is particularly suggested using PE-X pipes. The two tightening keys (d.16-63 and d.75-110) are important tools to install the **MAGNUM 3G** fittings