

Optical position indicator



Reference	tooltiplmage	system	Category	family	To be used with:	DN
OPI01	-	Special parts and accessories	Accessories for actuated valves	Accessories for pneumatic valves	FE/FK DA	40 ÷ 150
OPI02	-	Special parts and accessories	Accessories for actuated valves	Accessories for pneumatic valves	FE/FK DA	200 ÷ 300
OPI03	-	Special parts and accessories	Accessories for actuated valves	Accessories for pneumatic valves	FK/DA	350 ÷ 400
OPI04	-	Special parts and accessories	Accessories for actuated valves	Accessories for pneumatic valves	FK NC	350 ÷ 400



Optical position indicator

- Upper part (PVC-U)
 - Bottom part (PVC-U)
 - Bolts (zinc plated steel)
 - Nuts (zinc plated steel)
 - Gasket (NBR)
 - Reinforcing ring (Stainless steel)
- The reinforcing bush are used to reinforce the pipe PE100 (SDR11) e PE-X, to elong the lifetime of the pipeline and to reduce the collapse risk of the pipe in disadvantages conditions. They use is particularly suggested using PE-X pipes. The two tightening keys (d.16-63 and d.75-110) are important tools to install the **MAGNUM 3G** fittings