

Flexible connector with flat ring

WITH FLAT JOINT. Flexible sleeve. Not for use with adhesives.(For difficult to reach areas. Not for use as a trap.)

Reference	tooltiplmage	characteristics	Box units	measurement	В	С	r	aMaxMin	figure
022066	-	A (445-255 mm)	50	11/4 X 32-40	32	40	11/4′′	445-255	А

