

# Mechanical clamping set (without screws)

Mechanical clamping set (without screws).



Reference	tooltiplmage	Box units	measurement
031437	-	1	650X70
031438	-	1	750X70
031439	-	1	950X70
031513	-	1	350X70
031514	-	1	550X70
031515	-	1	850X70