

Female threaded coupling



Reference	tooltipImage	characteristics	Box units	measurement
355005	-	Without metal reinforcement	25	50-11/2
355006	-	Without metal reinforcement	25	63-2
355035	-	Without metal reinforcement	100	20-1/2
355036	-	Without metal reinforcement	100	25-3/4
355037	-	Without metal reinforcement	100	32-1
355038	-	Without metal reinforcement	50	40-11/4
355039	-	Without metal reinforcement	5	75-21/2
355040	-	Without metal reinforcement	5	90-3
355134	-	Without metal reinforcement	50	25-1/2
355144	-	With metal reinforcement	25	63-2
355145	-	With metal reinforcement	5	75-2 1/2
355146	-	With metal reinforcement	5	90-3
355169	-	With metal reinforcement	100	20-1/2
355170	-	With metal reinforcement	50	25-1/2
355171	-	With metal reinforcement	100	25-3/4
355172	-	With metal reinforcement	100	32-1
355173	-	With metal reinforcement	50	40-11/4
355174	-	With metal reinforcement	25	50-11/2
355193	-	Without metal reinforcement	2	110-4
355226	-	With metal reinforcement	2	90-3
355246	-	Without metal reinforcement	50	25-1

Female threaded coupling

Reference	tooltplmage	characteristics	Box units	measurement
355247	-	With metal reinforcement	50	25-1
7355035	-	Without metal reinforcement	50	20-1/2
7355036	-	Without metal reinforcement	50	25-3/4
7355037	-	Without metal reinforcement	50	32-1
7355134	-	Without metal reinforcement	25	25-1/2
7355169	-	With metal reinforcement	25	20-1/2
7355170	-	With metal reinforcement	25	25-1/2
7355171	-	With metal reinforcement	25	25-3/4
7355172	-	With metal reinforcement	20	32-1
7355246	-	Without metal reinforcement	25	25-1
7355247	-	With metal reinforcement	25	25-1