

# Saddle single outlet (2 bolts)

BSP clamp saddle.



Reference	tooltiplmage	Box units	measurement
053001	-	50	40-1/2"
053002	-	50	40-3/4"
053003	-	50	40-1"
053004	-	50	50-1/2"
053005	-	50	50-3/4"
053006	-	50	50-1"
053041	-	100	32-1/2"
053042	-	100	32-3/4"
053133	-	100	25-1/2"
053135	-	100	32-1"