

Reducing cross branch

Reducing cross branch.



Reference	tooltiplmage	characteristics	Box units	measurement
055129	-	N AENOR	15	40-32
055130	-	N AENOR	10	50-40
055131	-	N AENOR	10	63-50