


Repair work union. Solvent socket.

Repair work union. Solvent socket.



Reference	tooltiplmage	Box units	measurement
052633	-	30	50
052634	-	30	63